




























Арматура периодического профиля (А300, А400, А500, А550, А600, А800, А1000)

$d_{on} = 5d_s$ $\emptyset 6 \dots \emptyset 18$		$\emptyset 12$		$d_{on} = 8d_s$ $\emptyset 20 \dots \emptyset 40$		$\emptyset 28$	
$\emptyset 6$		$\emptyset 14$		$\emptyset 20$		$\emptyset 32$	
$\emptyset 8$		$\emptyset 16$		$\emptyset 22$		$\emptyset 36$	
$\emptyset 10$		$\emptyset 18$		$\emptyset 25$		$\emptyset 40$	

Арматура с гладким профилем (A240)

$d_{on} = 2,5d_s$ $\emptyset 6 \dots \emptyset 18$		$\emptyset 12$		$d_{on} = 4d_s$ $\emptyset 20 \dots \emptyset 40$		$\emptyset 28$	
$\emptyset 6$		$\emptyset 14$		$\emptyset 20$		$\emptyset 32$	
$\emptyset 8$		$\emptyset 16$		$\emptyset 22$		$\emptyset 36$	
$\emptyset 10$		$\emptyset 18$		$\emptyset 25$		$\emptyset 40$	